

APPENDIX A
SITE VISIT PHOTOGRAPHS



Photo 1: SWMU No. 1 – Former Sludge Drying Area in Southeast Corner



Photo 2: SWMU No. 2 – Former Sludge Drying Area in Southwest Corner, formerly Impoundments 317 and 317A



Photo 3: SWMU No. 3 – Sludge Roll-off



Photo 4: SWMU No. 4 – Filter Cake Roll-offs



Photo 5: SWMU No. 5 – Hazardous Waste Storage Area



Photo 6: SWMU No. 6 – Satellite Accumulation Areas



Photo 7: SWMU No. 7 – Safety-Kleen Parts Cleaners



Photo 8: SWMU No. 8 – Trash Compactor



Photo 9: SWMU No. 9 – Universal Waste Areas



Photo 10: SWMU No. 9 – Universal Waste Areas



Photo 11: SWMU No. 10 – Former Wastewater Treatment Lagoons and Impoundments, Settling Ponds 313/315, and Dilution Water Pond 316



Photo 12: SWMU No. 11 – Wastewater Treatment System



Photo 13: SWMU No. 12 – Former Separation Pond, Fire Pond 307



Photo 14: AOC No. 1 – Groundwater Contamination



Photo 15: AOC No. 2 – Sludge Roll-off Spill



Photo 16: AOC No. 3 – Heat Transfer Fluid Spill



Photo 17: AOC No. 4 – Benzoic Acid Release



Photo 18: AOC No. 5 – Hydrogen Peroxide Tank Leak